



\*\*\*\*

# ASP OPERATIONS & PROCEDURES





#### \*\*\*\*\*

### **Preparation**

- Units are expected to arrive at the ASP ready to conduct business. This includes: vehicle(s), load plan(s) appropriate amount of tie down straps, correct fire extinguishers, glove box edition, correct medical cert, OF 346, and all documentation.
- Units MUST do their due diligence the day prior to arriving at the ASP!





\*\*\*\*\*

### Most recent DISREPS:

## Supported Unit turn-in problems:

- Units returning misfires without being cleared/documented by EOD.
- Missing packaging/munition components. (Safe/Unsafe)
- Munitions not strapped to the vehicle properly.
- Excessive breakout.
- Vehicles not passing inspection.
- Strapping Ammunition loads. (Completely UNSAT)
- Mixing ammunition and dunnage.
- Incompatible loads\
- Vehicles placarded incorrectly.





#### \*\*\*\*


## Supported Unit Issue DISREPS:


- MEDCERTS
- No Ammo endorsement
- Incorrect fire extinguisher
- Missing Chock Blocks
- Missing placards
- Vehicles not passing inspection
- No load plan
- Not enough bed space
- Turn in followed by an Issue. Arriving too late.


















## Recent DISREPS

 The following pics were taken at the ASP over the last 30 days......

SAVE YOUR PACKING MATERIAL



CC-A PACKAGED WITH CC-H MATERIAL NO EOD DOCUMENTATION



Missing Packaging



Missing Pull PIN (ASP Inserted wire)



What's the worst that could happen? Ask yourself "How did we fail?"







# SKIDS NOT STRAPPED, ONLY ONE STRAP TO TRUCK


















NOT What it looks like...





\*\*\*\*







\*\*\*\*\*

Common Questions:

- Can I "Safe Haven"?
- Can I do an extended pre-stage?
- Do I need the same driver?
- What time do you stop doing Turn-ins?
- What happens if during my issue the ASP has lightning within 10 miles?





#### \*\*\*\*\*

- All steps are adjustable.
- Most problems/discrepancies could be prevented with a phone call.
- POC's:
- OIC CWO4 Fouchi 451-4721
- Ops Chief MGySgt Maras 451-4723
- AOIC Mr. Nyman 451-4722
- RSI Chief MSgt Newsum 451-4738